

DRIVES






















shaft distortion caused by misalignment




- naeven notor to stator air gap cyclic fatigae of notor component excessive radial and arial forces transmitted to bearings • shaft scal mbbing beavier on one side











Common Alignment Problems















COUPLINGS















One-piece rigid couplings wrap around the shaft providing high torsional holding power without the shaft damage and fretting inherent when set screw style couplings are used.



Two-piece styles have the additional benefits of allowing for disassembly and maintenance without removal of other components.