


Basic Engineering Drawing

Paper Sizes

- **All engineering drawings are printed on paper.**
- **The size depends on the size and scale of the component.**
- **The metric A series of paper is normally used as it is standard throughout Europe and most of the world. The actual sheet sizes (in millimetres) are as follows:**
 - **A0 841 x 1189 (1m²)**
 - **A1 594 x 841**
 - **A2 420 x 594**
 - **A3 297 x 420**
 - **A4 210 x 296**

Paper Sizes (cont)

- **Note that each sheet size is half the previous one**



Title block

The paper on which engineering drawing are produced is normally surrounded by a bold border called a **frame**.

At the lower right-hand corner of the frame there should be a **title block**; the title block must contain a minimum of six items in order to conform to BS 308 guidelines.

- Draughtspersons name or title (DRAWN)
- Date of drawing
- Projection symbol
- Scale ratio
- Component title
- Drawing number
- Further information is nearly always required.

Title block (cont)

- A typical blank drawing-page layout is illustrated below.

WHEN IN DOUBT - ASK		PROJECTION	SCALE	DATE
SURFACE FINISH ✓ μm				
DRAWN	UNITS	LIMITS	MATERIAL	
TITLE			NUMBER	

Verification of drawings

- **It is good practice to check that any drawings being used is current.**
- **Engineering drawings are often altered to update specifications, standards and sizes.**
- **It is important to ensure the drawing being used is the most recent issue for all work.**
- **This verification should be carried out if there is any doubt about the correctness of the drawing or its content.**

Methods of verifying engineering drawings

- **Check the date of issue on the drawing.**
- **See if there is an expiry date.**
- **Ask your supervisor if you have any doubts.**
- **Contact the draughtsperson (where possible) if any doubt persists**

Types of lines

- Various features on engineering drawings are represented by particular lines.
- The table below shows the correct type of line for several applications as recommended in BS 308.
- The correct type of line should always be used.

<i>Line</i>	<i>Description</i>	<i>Application</i>	<i>Key</i>
	Continuous bold	Visible outlines Visible edges	a b
	Continuous fine	Dimension lines Leader lines Projection lines Hatching Adjacent part outlines	c d e f *
	Continuous fine, irregular	Limit of partial view	g
	Fine short dashes	Hidden edges Hidden outlines	h *
	Fine chain	Centre lines	i
	Fine chain, bold at ends and changes of direction	Cutting planes	j


* Not illustrated in Exercise 3.1.

Orthographic projection

- **Designers need to represent components clearly on paper in the form of drawings if they are to be manufactured as required.**
- **The preferred methods of drawing components for manufacture is to set two or more views of them on paper in a logical manner using a drawing system called orthographic projection**
- **There are two types of orthographic projection; first-angle orthographic projection (first-angle projection) and third angle orthographic projection (third-angle projection)**


First-angle projection

- This is constructed by looking at the component and selecting the faces which reveal the most features. Consider the corner plate shown here. It could be viewed in any of the six planes shown.



First– angle projection (cont)


- Examination reveals that views A, B and C show the greatest number of visible edges whereas views D, E and F leave some of the details obscured.
 - Three views are generally chosen and the preferred views A, B and C have been selected here as the most appropriate for a first-angle projection of the corner plate.
 - For the correct layout of the corner plate in first-angle projection, the procedure is as follows:
1. The elevation considered to reveal the most features is drawn. For the purpose of this exercise, view A is chosen




View A

First– angle projection (cont)

2. View B is then drawn to the **left** of view A. Note that view B is drawn **opposite** the side from which it is viewed (arrow B).




3. View C is drawn directly **below** view A. Note that view C is drawn **opposite** the side from which it is viewed (arrow C).




First– angle projection (cont)

If you consider view B to be the face with the most detail, then the first-angle projection would be drawn like this:



The British standard symbol for first-angle projection is shown below. This symbol must be included in the title block whenever first-angle projection is used.




Third– angle projection

- **Third-angle projection (American projection) is an alternative method of laying out the individual views on the page**
- **When using this projection we use the same planes of projection as described for first-angle projection, but the views are not laid out on the same side as they are viewed from.**
- **A drawing of the corner plate in third-angle projection is constructed as follows:**


Third– angle projection (cont)

1. The elevation considered to reveal the most features is drawn. For the purpose of this exercise, view A is chosen



View A


2. View B is drawn on the **right** of view A. Note that view B is drawn **on** the side from which it is viewed (arrow E)




View B

Third– angle projection (cont)

3. View C is drawn directly **above** view A.
Note that view C is drawn **on** the side
from which it is viewed (arrow C)




If you consider view B to have the most detail, then the third-angle projection of the corner plate would be laid out like this:



Third– angle projection (cont)

- **The British Standard symbol for third-angle projection is shown below. This symbol must be included in the title block whenever third-angle projection is used.**



Dimensioning drawings

An engineering drawing contains information about the shape of a component.


It also shows dimensions regarding the sizes and the limits to which the component should be manufactured

All dimensions are in millimetres (mm) unless otherwise stated

Information regarding dimensions must be clear and in accordance with BS 308, the fundamental requirements of which are described below:


- **When applying dimensions to a drawing, use thin continuous dimension lines, projection lines and leaders.**
- **Arrowheads on dimension lines and leaders must be solid and slender.**
- **Dimension lines should not cross each other.**
- **When adding notes to a drawing, the letters, numbers and symbols should be bold and clear, not less than 3mm in height. Capital letters are generally preferred.**

Dimensioning drawings (cont)




Dimensioning drawings (cont)

- When applying dimensions to a drawing, all distances in each direction must be taken from the same face, line or point. This face, line or point is called a datum.
- The height, length and width measurements all have separate datum's.
- **Note:** On these three examples only one type of datum is shown for each drawing. In practice a drawing may show more than one type of datum e.g. a datum line and a datum face.




Datum faces

Also known as datum edges, they are the most common type of datum. All lengths are dimensioned from face A, all heights from face B



Datum lines

All dimensions are relative to a line. Lengths are dimensioned from Line A, heights from Line B




Datum points

Used to dimension features which all have the same reference point, P


Dimensioning drawings (cont)

- The symbol \varnothing preceding a dimension indicates a diameter.
- There are several methods of dimensioning circles. Choose according to the size and location of the circle, and whether dimensioning a hole or a shaft.






Dimensioning drawings (cont)




- Dimensions and text should be placed outside the drawing outline wherever possible



Dimensioning drawings (cont)




- The text should be centred above the dimension lines so it can read from the bottom or the right-hand side of the drawing.
- When dimensioning a radius (curved surface), use a leader and the abbreviation R to precede the size of the curve's radius.
- Each dimension should be given only once and should be as close as possible to the relevant feature.
- The illustrated method is recommended for stating size limits of an individual dimension. Note that both the max and min permissible sizes are shown.
- Metric screw threads are specified by the letter M followed by the diameter of the thread (M8), a x sign then the pitch of the thread (1.25), giving M8 x 1.25.




Dimensioning drawings (cont)

- Holes for fasteners or for locating devices should be dimensioned by one of the alternative methods shown for each type of hole.




- When indicating that a surface is to be machined, the machining symbol is drawn on the surface of its projection.
- If a specific surface texture is required, the roughness average (Ra) value is written on top of the machining symbol. The illustrated surface is to be machined to an Ra of 3.2um




Sectioning

- **A section elevation may be of benefit when a drawing contains so much hidden detail that it has become unclear.**
- **A sectional elevation is a view of part of a component when viewed on a cutting plane.**
- **The cutting plane on engineering drawings is shown as a fine chain line with thick ends; the viewing direction is indicated by two arrows against these ends with identifying letters e.g. A-A.**


Sectioning (cont)




Diagrammatic view of cutting plane A-A



Cam flange



End view in first-angle projection



Section A-A

- **Consider the cam flange shown above. When the end view is drawn in first-angle projection, the resulting drawing contains much hidden detail.**
- **Compare this with the sectional view A-A, this would be seen if the cam flange were viewed on the cutting plane.**
- **View A-A shows more clearly the wall thickness of the tube, the shape of the cam and the positions of the holes in the right-hand flange**
- **The area through which the cutting plane passes is hatched with fine lines drawn at 45°, usually about 4mm apart**

Sectioning (cont)

The layout of a sectional view is always in accordance with the rules for orthographic projection.


For example, the cam flange shown is in first-angle projection, i.e. it is viewed in the direction of the arrows A, so the sectional view is drawn opposite the side from which it is viewed.

Do not hatch these features when cutting plane passes lengthways through them:

- **Webs (supporting ribs)**
- **Fasteners (nuts, bolts and washers etc.)**
- **Shafts**
- **Thin sheets**


Sectioning (cont)

When a component is sectioned through a hole or other similar feature, the hatching lines on all the areas of that component have the same pitch (spacing) and angle.




Unhatched items – the web, the shaft, and the fasteners

For clarification the pitch of the hatching lines can be adjusted as long as the pitch remains constant for any single component



These drawings are the component parts of a pulley mounting bracket.

Sectional assembly (cont)




Sectioned assembly looking on cutting plane C-C of the pulley mounting bracket above. Note that the pin, nut and washer are not hatched

Isometric projection

- **This is used when a pictorial shape of the finished object is required.**
- **This type of projection shows a 3D like image, which is easier to visualise than an orthographic drawing.**
- **It is used extensively in books and catalogues as it can be understood by non-engineers.**
- **Isometric drawings are not always used for production so dimensions are not always included.**

Isometric projection (cont)

- On isometric drawings all horizontal lines on the X and Y planes are drawn at 30°.
- Vertical lines are drawn vertically
- All lines are drawn to a constant scale
- An example of a component in isometric projection is shown below.



How to sketch isometric circles

1. Draw an isometric box ABCD which the circle will fit inside.
2. Insert the longest diagonal BC of the isometric box.
3. Draw a line AF and DE from each obtuse-angled corner (those with angles greater than 90°) of the isometric box, to the midpoint of the opposite line. These lines pass through the diagonal.
4. From the obtuse-angled corners (A and D) strike two arcs with a compass. The compass point located at point A for the first arc, at point D for the second.
5. From the points of intersection (G and H) of the short lines with the long diagonal (BC), strike two arcs. The compass point is located at point G for the first arc, at point H for the second.
6. Erase all construction lines.

