



Typical Weld Joints, Sections & Symbols


BUTT (Groove Weld)




EDGE



CORNER



LAP



T

