

## ***Ultrasonic Level Practical Exercise***

***Aim***     ***To calibrate a Prosonic FMU 861 Ultrasonic Level Detector***

Determine what the type of level application the measurement is. V0H3

Select level distance unit. V8H3

Measure the distance from the base of the vessel to the bottom of the transducer. V0H1

Measure the distance from the bottom of the transducer to the high level mark. V0H2

Using the attached matrix enter the values into the correct memory locations